From: <u>Downham, Todd</u>

To: <u>Coltrain, Katrina</u>; <u>McMillan, Teresa</u>

Cc: <u>lvega\_eaest.com</u>

Subject: RE: Wilcox TO 128 - Tap Sampling
Date: Thursday, June 16, 2016 3:45:42 PM

Attachments: <u>image001.png</u>

image002.png image003.png image005.png

Domestic Well Locations.sbn
Domestic Well Locations.sbx
Domestic Well Locations.shp
Domestic Well Locations.shp.xml
Domestic Well Locations.shx
Domestic Well Locations.cpg
Domestic Well Locations.dbf
Domestic Well Locations.prj
Wilcox Well Sampling3.pdf

I don't have GPS data on the well locations, however I have created a Shapefile for the well locations that is very accurate. See attached shapefile and figure.

## Hope this helps

Todd Downham
Environmental Programs Specialist



Department of Environmental Quality Site Remediation Section Land Protection Division (405) 702-5136

todd.downham@deq.ok.gov



From: Coltrain, Katrina [mailto:coltrain.katrina@epa.gov]

**Sent:** Thursday, June 16, 2016 6:48 AM **To:** McMillan, Teresa; Downham, Todd

Cc: lvega\_eaest.com

Subject: RE: Wilcox TO 128 - Tap Sampling

There are two well located at GW-01/02; but one is dry. Hence the second well. As for GW-08, I am not certain but I believe it is one well and the GPS location is wrong.

Todd, don't you have GPS for this well?

Katrina Higgins-Coltrain Remedial Project Manager US EPA Region 6 LA/OK/NM Section (6SF-RL) 1445 Ross Avenue Dallas, Texas 75202 214-665-8143 From: McMillan, Teresa [mailto:tmcmillan@eaest.com]

**Sent:** Wednesday, June 15, 2016 6:16 PM

**To:** Downham, Todd < <a href="mailto:Todd.Downham@deq.ok.gov">To: Downham, Todd < <a href="mailto:Todd.Downham@deq.ok.gov">Todd.Downham@deq.ok.gov</a>>; Coltrain, Katrina < <a href="mailto:coltrain.katrina@epa.gov">coltrain.katrina@epa.gov</a>>

**Cc:** lvega\_eaest.com < lvega@eaest.com > **Subject:** RE: Wilcox TO 128 - Tap Sampling

Are there two wells located at EA's GW-01/02 location and are there two wells at GW-08 location or where you doing duplicates and naming them a blind well name?

Teri McMillan, PG EA Engineering, Science, and Technology, Inc., PBC 320 Gold Ave SW, Suite 1300 Albuquerque, New Mexico 87102 (505) 715-4332

**From:** Downham, Todd [mailto:Todd.Downham@deq.ok.gov]

**Sent:** Wednesday, June 15, 2016 11:48 AM

**To:** 'Coltrain, Katrina' < coltrain.katrina@epa.gov>

**Cc:** McMillan, Teresa < <a href="mailto:tmcmillan@eaest.com">tmcmillan@eaest.com</a>>; Vega, Luis < <a href="mailto:lvega@eaest.com">tvega@eaest.com</a>>

**Subject:** RE: Wilcox TO 128 - Tap Sampling

I have several comments on figure 14:

- 1. GW-8 is in the wrong location (the other figure is incorrect). The residence is located to the south and cut off of the aerial photo in the figure.
- 2. GW-14 may not be an option to sample. Will need to be field verified.
- 3. The residential well located on the furthest northern edge of the north tank farm should be added.
- 4. A well located at the south east residence on the Wilcox processing area might be able to be sampled. Would need to be field verified.

Attached is a map with well locations indicated. Some of the nomenclature is for DEQ sampling purposes, so disregard those designations.

Thank you.

Todd Downham Environmental Programs Specialist



Department of Environmental Quality Site Remediation Section Land Protection Division (405) 702-5136 todd.downham@deq.ok.gov



From: Coltrain, Katrina [mailto:coltrain.katrina@epa.gov]

Sent: Wednesday, June 15, 2016 9:51 AM

To: Downham, Todd

Cc: Teri Mcmillan (<a href="mailto:tmcmillan@eaest.com">tmcmillan@eaest.com</a>); lvega\_eaest.com

Subject: FW: Wilcox TO 128 - Tap Sampling

Please assist with EA's question. thanks

Katrina Higgins-Coltrain Remedial Project Manager US EPA Region 6 LA/OK/NM Section (6SF-RL) 1445 Ross Avenue Dallas, Texas 75202 214-665-8143

From: McMillan, Teresa [mailto:tmcmillan@eaest.com]

Sent: Wednesday, June 15, 2016 9:19 AM

**To:** Coltrain, Katrina < coltrain.katrina@epa.gov>

**Cc:** lvega\_eaest.com < lvega@eaest.com> **Subject:** Wilcox TO 128 - Tap Sampling

Katrina,

Would it be ok to send the attached to Todd for clarification on the location of our GW-08 (Figure 14)? We placed our GW-08 in the location of LWGW-8 (see attached figures). However, during the call Todd had said that he remembered GW-08 as a location further south. If I could get clarification that would be great.

Thanks,

Teri McMillan, PG EA Engineering, Science, and Technology, Inc., PBC 320 Gold Ave SW, Suite 1300 Albuquerque, New Mexico 87102 (505) 715-4332

## **TARGET SHEET**

SITE NAME: W	ILCOX OIL COMPANY	
CERCLIS I.D.:	OK0001010917	
TITLE OF DOC.:	DOMESTIC_WELL_LOCATIONS.SBN; DOMESTIC_W DOMESTIC_WELL_LOCATIONS.SHP; DOMESTIC_W DOMESTIC_WELL_LOCATIONS.SHX; DOMESTIC_W DOMESTIC_WELL_LOCATIONS.DBF; DOMESTIC_W	/ELL_LOCATIONS.SHP.XML /ELL_LOCATIONS.CPG;
DATE OF DOC.:		06/16/2016
NO. OF PGS. THIS	S TARGET SHEET REPLACES:	UNKNOWN
SDMS #:	9813190 RELATED #:	
CONFIDENTIAL ?	MISSING PAGES ?	
ALTERN. MEDIA	? X CROSS REFERENCE ?	
LAB DOCUMENT	? LAB NAME:	
ASC./BOX #:		
CASE #:	SDG #:	
_		

THESE FILES ARE OF AN UNKNOWN OR UNSUPPORTED

**COMMENTS:** FORMAT AND CONNOT BE OPENED AT THIS TIME.